



1131 VIA CALLEJON, SAN CLEMENTE, CA 92673

Inspect all original flat washers for damage on the face area that had contact with the metal sleeve of the old engine mount.

Replace all washers that have any wear on the sleeve contact area.

© 2007 Energy Suspension. All rights reserved.
May not be reproduced, in any form, or by any means,
without the written consent of Energy Suspension.

17101

16/APR/07 BRH